

## **SCC #24 and #25 APPROVED 6 APR 99**

### **MIL-STD-188-220B**

#### **Typographical Errors:**

##### **SCC#24**

- There are 3 spelling mistakes in paragraph 2.1: "specifried" (specified), "stnadard" (standard), "documens" (documents).

##### **SCC#25**

There are a number of typographical errors in Section 5 that were approved:

- There are two pages labeled 5-30. Change the first one to 5-29.
- Remove the extra character 'l' following the word "embedded" in the Figure 4b title.
- In paragraph 5.4.1.1.2.1, the RFC for ARP is designated 8268. It should be changed to 826.
- In paragraph 5.2.1.2, there is a reference to C3.2b. The proper reference should be C3.2.2.
- A sentence will be added to Paragraph 5.3.6.1.5 stating "This paragraph is left blank to maintain paragraph conformity".